

Errata to

Procedural Standard for Fume Hood

Performance Testing – 2016

Second Edition

Correction Sheet #2 – replaces Correction Sheet #1, dated July 2018
Issued 01 July 2022

Copyright © 2022 by NEBB®

All rights reserved. Published 2022. Printed in the United States of America. These correction sheets may be freely reproduced and distributed in order to maintain the utility and currency of the underlying Standard. These correction sheets may not be sold, licensed, or otherwise distributed for any commercial purposes whatsoever. The content of these correction sheets may not be modified.

The corrections listed on this errata sheet apply to copies of Procedural Standard for Fume Hood Performance Testing, Second Edition - 2016.

Erratum #1

Page 14, Sub Section 5.2.6 Instrument Calibration states:

5.2.6 INSTRUMENT CALIBRATION

This is a listing of the instruments that will be used to verify the reported data including instrument type, manufacturer, model number, serial number and calibration date.

Page 14, subsection 5.2.6., Instrument Calibration is revised to the following verbiage:

5.2.6 INSTRUMENT CALIBRATION

The Final Report must contain a summary list of all instrumentation and equipment used on the project accompanied by copies of the current calibration certificates.

Erratum #2

Page 11, Section 4, subsection 4.3 Calibration states:

4.3 CALIBRATION

All fume hood performance testing instrumentation shall be calibrated, at a minimum annually, in accordance with the manufacturer's recommendations by a testing laboratory traceable to the National Institute of Standards and Technology or equivalent institute in countries other than the The United States.

Firms with multiple sets of instrumentation shall calibrate all instrumentation used by the firm on FHT projects in accordance with Table 4-1 as a minimum requirement for NEBB Firm certification.

Page 11, Section 4, Subsection 4.3 **CALIBRATION** was changed to the following:

4.3 CALIBRATION

Please refer to the NEBB website (www.nebb.org) for the current NEBB FHT Required Instrumentation List.

Erratum #3

Delete page 12, Table 4-1 (**NEBB MINIMUM FHT INSTRUMENTATION REQUIREMENTS**).